

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Page County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
8B: Judson-----	90	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
9B: Marshall-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
9B2: Marshall-----	100	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
9C: Marshall-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
9C2: Marshall-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
11B: Colo-----	65	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00  0.50
Judson-----	35	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
24D: Shelby-----	90	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Slope Too clayey	0.63  0.50
24D2: Shelby-----	100	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Slope Too clayey	0.63  0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Page County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
24E: Shelby-----	95	Very limited Depth to saturated zone Slope Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone Slope	1.00 1.00	Very limited Slope Too clayey	1.00 0.50
24E2: Shelby-----	100	Very limited Depth to saturated zone Slope Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone Slope	1.00 1.00	Very limited Slope Too clayey	1.00 0.50
24F2: Shelby-----	100	Very limited Depth to saturated zone Slope Too clayey	1.00 1.00 0.50	Very limited Slope Depth to saturated zone	1.00 1.00	Very limited Slope Too clayey	1.00 0.50
41D: Sparta-----	90	Very limited Seepage Too Sandy Slope	1.00 1.00 0.16	Very limited Seepage Slope	1.00 0.16	Very limited Seepage Too Sandy Slope	1.00 0.50 0.16
43: Bremer-----	85	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Hard to compact Too clayey	1.00 1.00 0.50
54: Zook-----	90	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey Hard to compact	1.00 1.00 1.00

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Page County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
54+: Zook-----	100	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	1.00
		Too clayey	1.00				
76B: Ladoga-----	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
		Too clayey	0.50				
76C: Ladoga-----	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
		Too clayey	0.50				
76C2: Ladoga-----	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
		Too clayey	0.50				
76D: Ladoga-----	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Slope	0.63
		Slope	0.63	Slope	0.63	Too clayey	0.50
		Too clayey	0.50				
76D2: Ladoga-----	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Slope	0.63
		Slope	0.63	Slope	0.63	Too clayey	0.50
		Too clayey	0.50				
88: Nevin-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
		Too clayey	0.50			Depth to saturated zone	0.09

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Page County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
93D: Shelby-----	50	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Slope Too clayey	0.63  0.50
Adair-----	40	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Depth to saturated zone Slope Too clayey	0.86  0.63 0.50
93D2: Shelby-----	50	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Slope Too clayey	0.63  0.50
Adair-----	40	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Depth to saturated zone Slope Too clayey	0.86  0.63 0.50
93E2: Shelby-----	50	Very limited Depth to saturated zone Slope Too clayey	1.00  1.00 0.50	Very limited Depth to saturated zone Slope	1.00  1.00	Very limited Slope Too clayey	1.00  0.50
Adair-----	40	Very limited Depth to saturated zone Slope Too clayey	1.00  1.00 0.50	Very limited Depth to saturated zone Slope	1.00  1.00	Very limited Slope Depth to saturated zone Too clayey	1.00  0.86 0.50
99C: Marshall-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
99C2: Marshall-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Page County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
99D: Marshall-----	90	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
99D2: Marshall-----	90	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
133: Colo-----	85	Very limited Flooding  Depth to saturated zone Too clayey	1.00  1.00 0.50	Very limited Flooding  Depth to saturated zone	1.00  1.00	Very limited Depth to saturated zone Too clayey	1.00  0.50
133+: Colo-----	85	Very limited Flooding  Depth to saturated zone Too clayey	1.00  1.00 0.50	Very limited Flooding  Depth to saturated zone	1.00  1.00	Very limited Depth to saturated zone Too clayey	1.00  0.50
172: Wabash-----	95	Very limited Flooding  Depth to saturated zone Too clayey	1.00  1.00 1.00	Very limited Flooding  Depth to saturated zone	1.00  1.00	Very limited Depth to saturated zone Too clayey  Hard to compact	1.00  1.00  1.00
179D: Gara-----	95	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Slope Too clayey	0.63 0.50
179D2: Gara-----	95	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Slope Too clayey	0.63 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Page County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
179E2: Gara-----	95	Very limited Depth to saturated zone Slope Too clayey	1.00  1.00 0.50	Very limited Depth to saturated zone Slope	1.00  1.00	Very limited Slope Too clayey	1.00  0.50
179F2: Gara-----	95	Very limited Depth to saturated zone Slope Too clayey	1.00  1.00 0.50	Very limited Slope Depth to saturated zone	1.00  1.00	Very limited Slope Too clayey	1.00  0.50
179G2: Gara-----	95	Very limited Depth to saturated zone Slope Too clayey	1.00  1.00 0.50	Very limited Slope Depth to saturated zone	1.00  1.00	Very limited Slope Too clayey	1.00  0.50
192C: Adair-----	90	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone Too clayey	0.86  0.50
192C2: Adair-----	90	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone Too clayey	0.86  0.50
192D: Adair-----	100	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Depth to saturated zone Slope Too clayey	0.86  0.63 0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Page County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
192D2: Adair-----	90	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Depth to saturated zone Slope Too clayey	0.86  0.63 0.50
212: Kennebec-----	85	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Not limited	
220: Nodaway-----	85	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Not limited	
248: Wabash-----	95	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey Hard to compact	1.00 1.00 1.00
248+: Wabash-----	95	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey Hard to compact	1.00 1.00 1.00
273B: Olmitz-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
273C: Olmitz-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Page County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
370: Sharpsburg-----	100	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
370B: Sharpsburg-----	100	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
370B2: Sharpsburg-----	100	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
370C: Sharpsburg-----	100	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
370C2: Sharpsburg-----	100	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
370D: Sharpsburg-----	100	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Slope Too clayey	0.63  0.50
370D2: Sharpsburg-----	100	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Slope Too clayey	0.63  0.50



Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Page County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
692C2: Mayberry-----	90	Very limited Depth to saturated zone Too clayey	1.00  1.00	Very limited Depth to saturated zone	1.00	Very limited Too clayey  Depth to saturated zone	1.00  0.86
692D: Mayberry-----	90	Very limited Depth to saturated zone Too clayey  Slope	1.00  1.00  0.63	Very limited Depth to saturated zone Slope	1.00  0.63	Very limited Too clayey  Depth to saturated zone Slope	1.00  0.86  0.63
692D2: Mayberry-----	90	Very limited Depth to saturated zone Too clayey  Slope	1.00  1.00  0.63	Very limited Depth to saturated zone Slope	1.00  0.63	Very limited Too clayey  Depth to saturated zone Slope	1.00  0.86  0.63
715: Alluvial Land-----	90	Not rated		Not rated		Not rated	
751C: Northboro-----	90	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
751C2: Northboro-----	90	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
751D: Northboro-----	90	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Slope Too clayey	0.63  0.50

Sanitary Facilities - Part 2.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Page County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
751D2: Northboro-----	90	Very limited Depth to saturated zone Slope Too clayey	1.00  0.63 0.50	Very limited Depth to saturated zone Slope	1.00  0.63	Somewhat limited Slope Too clayey	0.63  0.50
T9: Marshall-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
T9B: Marshall-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
T299: Minden-----	95	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
T368: Macksburg-----	90	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey Depth to saturated zone	0.50  0.09
T369: Winterset-----	90	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00  0.50
T370B: Sharpsburg-----	100	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50
T370C: Sharpsburg-----	100	Very limited Depth to saturated zone Too clayey	1.00  0.50	Very limited Depth to saturated zone	1.00	Somewhat limited Too clayey	0.50